1	EDMUND G. BROWN JR., Attorney General of the State of California		
2	ALFREDO TERRAZAS Senior Assistant Attorney General		
3	KAREN B. CHAPPELLE, State Bar No. 141267		
4	Supervising Deputy Attorney General 300 So. Spring Street, Suite 1702		
5	Los Angeles, CA 90013 Telephone: (213) 897-8944		
6	Facsimile: (213) 897-1071	,	
7	Attorneys for Complainant		
8	BEFORE THE		
9	DEPARTMENT OF CONSUMER AFFAIRS FOR THE BUREAU OF AUTOMOTIVE REPAIR		
10	STATE OF CALI	FORNIA	
11	In the Matter of the Accusation Against:	Case No. 70/00 07	
12	RHO'S AUTO REPAIR	Case No. 79/09-03	
13	JAMES MYONG HWAN RHO, a.k.a. MYONG RHO, OWNER	ACCUSATION	
14	1520 W. Cowles Street Long Beach, CA 90813		
15	Automotive Repair Dealer Reg. No. ARD 156930	SMOG CHECK	
16	Smog Check Station License No. RC 156930 Official Lamp Station License No. LS 156930		
17	Official Brake Station License No. BS 156930		
18	and		
19	MYONG RHO 5937 Los Nietos Street		
20	Buena Park, CA 90620		
21	Advanced Emission Specialist Technician License No. EA 111627		
22	Lamp Adjuster License No. LA 111627 Brake Adjuster License No. BA 111627		
23			
24	Respondents.		
25	· ///		
26	/// ///		
27	/// ///		
21			

Complainant alleges:

PARTIES

1. Sherry Mehl ("Complainant") brings this Accusation solely in her official capacity as the Chief of the Bureau of Automotive Repair ("Bureau"), Department of Consumer Affairs.

Rho's Auto Repair:

- 2. In or about 1990, the Director of Consumer Affairs ("Director") issued Automotive Repair Dealer Registration ("registration") Number ARD 156930 (formerly AL 156930) to James Myong Hwan Rho, also known as Myong Rho ("Respondent"), owner of Rho's Auto Repair. On October 4, 1999, Respondent's registration was revoked; however, the revocation was stayed and Respondent was placed on probation for a period of three years under terms and conditions, as set forth in paragraph 67 below. Respondent's registration was also suspended for ten days. Respondent's registration was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2008, unless renewed.
- 3. On or about December 20, 1990, the Director issued Smog Check Station License Number RC 156930 (formerly RL 156930) to Respondent. Respondent's smog check station license was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2008, unless renewed.
- 4. On or about December 20, 1990, the Director issued Official Lamp Station License Number LS 156930 (formerly LL 156930) to Respondent. On October 4, 1999, Respondent's lamp station license was revoked; however, the revocation was stayed and Respondent was placed on probation for a period of three years under terms and conditions, as set forth in paragraph 67 below. Respondent's lamp station license was also suspended for ten days. Respondent's lamp station license was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2008, unless renewed.
- 5. On or about December 20, 1990, the Director issued Official Brake Station License Number BS 156930 (formerly BL 156930) to Respondent. On October 4, 1999, Respondent's brake station license was revoked; however, the revocation was stayed and

Respondent was placed on probation for a period of three years under terms and conditions, as set forth in paragraph 67 below. Respondent's brake station license was also suspended for ten days. Respondent's brake station license was in full force and effect at all times relevant to the charges brought herein and will expire on November 30, 2008, unless renewed.

Myong Rho:

- 6. In or about 1996, the Director issued Advanced Emission Specialist Technician License Number EA 111627 to Respondent. Respondent's advanced emission specialist technician license was in full force and effect at all times relevant to the charges brought herein and will expire on June 30, 2008, unless renewed.
- 7. In or about 1998, the Director issued Lamp Adjuster License Number LA 111627 (formerly RY 111627) to Respondent. On October 4, 1999, Respondent's lamp adjuster license was revoked; however, the revocation was stayed and Respondent was placed on probation for a period of three years under terms and conditions, as set forth in paragraph 67 below. Respondent's lamp adjuster license was also suspended for ten days. Respondent's lamp adjuster license was in full force and effect at all times relevant to the charges brought herein and will expire on June 30, 2009, unless renewed.
- 8. In or about 1998, the Director issued Brake Adjuster License Number BA 111627 (formerly JC 111627) to Respondent. On October 4, 1999, Respondent's brake adjuster license was revoked; however, the revocation was stayed and Respondent was placed on probation for a period of three years under terms and conditions, as set forth in paragraph 67 below. Respondent's brake adjuster license was also suspended for ten days. Respondent's brake adjuster license was in full force and effect at all times relevant to the charges brought herein and will expire on June 30, 2008, unless renewed.

JURISDICTION

- 9. Business and Professions Code ("Bus. & Prof. Code") section 9884.7 provides that the Director may invalidate an automotive repair dealer registration.
- 10. Bus. & Prof. Code section 9884.13 provides, in pertinent part, that the expiration of a valid registration shall not deprive the Director of jurisdiction to proceed with a

2

3

4

5

6

7

8

11

28

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
2425	
26	
27	///

(c) Notwithstanding subdivision (b), the director may refuse to validate, or may invalidate temporarily or permanently, the registration for all places of business operated in this state by an automotive repair dealer upon a finding that the automotive repair dealer has, or is, engaged in a course of repeated and willful violations of this chapter, or regulations adopted pursuant to it.

16. Bus. & Prof. Code section 9889.3 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article [Article 7 (commencing with section 9889.1) of the Automotive Repair Act] if the licensee or any partner, officer, or director thereof:

- (a) Violates any section of the Business and Professions Code which relates to his or her licensed activities.
- (c) Violates any of the regulations promulgated by the director pursuant to this chapter.
- (d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured.
- (h) Violates or attempts to violate the provisions of this chapter relating to the particular activity for which he or she is licensed . . .

17. Bus. & Prof. Code section 9889.16 states:

Whenever a licensed adjuster in a licensed station upon an inspection or after an adjustment, made in conformity with the instructions of the bureau, determines that the lamps or the brakes upon any vehicle conform with the requirements of the Vehicle Code, he shall, when requested by the owner or driver of the vehicle, issue a certificate of adjustment on a form prescribed by the director, which certificate shall contain the date of issuance, the make and registration number of the vehicle, the name of the owner of the vehicle, and the official license of the station.

18. Bus. & Prof. Code section 9889.22 states:

The willful making of any false statement or entry with regard to a material matter in any oath, affidavit, certificate of compliance or noncompliance, or application form which is required by this chapter [the Automotive Repair Act] or Chapter 5 (commencing with Section 44000) of Part 5 of Division 26 of the Health and Safety Code constitutes perjury and is punishable as provided in the Penal Code.

- 19. Bus. & Prof. Code section 9889.9 states that "[w]hen any license has been revoked or suspended following a hearing under the provisions of this article [Article 7 (commencing with section 9889.1) of the Automotive Repair Act], any additional license issued under Articles 5 and 6 of this chapter in the name of the licensee may be likewise revoked or suspended by the director."
 - 20. Bus. & Prof. Code section 22, subdivision (a), states:

"Board" as used in any provision of this Code, refers to the board in which the administration of the provision is vested, and unless otherwise expressly provided, shall include "bureau," "commission," "committee," "department," "division," "examining committee," "program," and "agency."

- 21. Bus. & Prof. Code section 477, subdivision (b), states, in pertinent part, that a "license" includes "registration" and "certificate."
 - 22. Health & Saf. Code section 44072.2 states, in pertinent part:

The director may suspend, revoke, or take other disciplinary action against a license as provided in this article if the licensee, or any partner, officer, or director thereof, does any of the following:

- (a) Violates any section of this chapter [the Motor Vehicle Inspection Program (Health and Saf. Code § 44000, et seq.)] and the regulations adopted pursuant to it, which related to the licensed activities.
- (c) Violates any of the regulations adopted by the director pursuant to this chapter.
- (d) Commits any act involving dishonesty, fraud, or deceit whereby another is injured . . .
- 23. Health & Saf. Code section 44072.8 states that when a license has been revoked or suspended following a hearing under this article, any additional license issued under this chapter in the name of the licensee may be likewise revoked or suspended by the director.

Cost Recovery

24. Bus. & Prof. Code section 125.3 provides, in pertinent part, that a Board may request the administrative law judge to direct a licentiate found to have committed a violation or violations of the licensing act to pay a sum not to exceed the reasonable costs of the investigation and enforcement of the case.

VIDEOTAPE SURVEILLANCE OF AUGUST 6, 2007

- 25. On August 6, 2007, a representative of the Bureau conducted a videotape surveillance operation of Respondent's facility. The surveillance videotape and information obtained from the Bureau's vehicle information database ("VID") revealed that Respondent issued electronic smog Certificate of Compliance #VJ326072C, certifying that between 1647 and 1656 hours, he had tested and inspected a 2003 Toyota truck, license #7E54377, and that the vehicle was in compliance with applicable laws and regulations. In fact, Respondent conducted the inspection on the 2003 Toyota truck using clean-piping methods¹, resulting in the issuance of a fraudulent certificate of compliance for the vehicle (Respondent used the exhaust emissions of another vehicle, a Toyota truck of an unknown year, license #8D12518, during the smog inspection).
- 26. The representative later determined that Respondent was issuing brake and lamp certificates during the time of the August 6, 2007, surveillance, as well as the surveillance operations of August 16, 2007, and August 21, 2007, as set forth below.
- 27. On September 11, 2007, the representative went to Respondent's facility and obtained invoices, brake and lamp certificates, and vehicle inspection reports issued by Respondent during the month of August 2007.
- 28. On September 17, 2007, the representative returned to the facility and obtained additional lamp certificates. The representative spoke with Respondent regarding his procedure for issuing a brake certificate to a vehicle. Respondent stated that he removes all of the wheels from each vehicle, performs a visual inspection of the brake components, measures the brake rotor/brake drum thickness and brake pad/brake lining thickness, and notes the measurements on the invoice for the vehicle. Respondent also stated that he performs a road test that measures how many feet are required to stop the vehicle at 20 miles per hour (mph).

///

^{1.} Pursuant to California Code of Regulations, title 16, section 3340.1, "clean piping" means the use of a sample of the exhaust emissions of one vehicle in order to cause the Test Analyzer System or Emission Inspection System to issue a certificate of compliance for another vehicle.

29. A review of the videotape of August 6, 2007, and the brake certificates issued by Respondent revealed the following: Respondent certified that he performed the applicable inspections of the brake system components on the vehicles identified below as specified by the Bureau and the vehicle manufacturer, and that each vehicle required 20 feet to stop at 20 mph. In fact, Respondent did not remove the wheels from any of the vehicles to measure the brake rotor/drum thickness or brake pad/lining thickness, did not perform a visual inspection of the brake systems on the vehicles, and did not road test any of the vehicles.

Time Vehicle Observed at Facility	Vehicle Certified & VIN No.	Brake Certificate Number
1. 0916 - 0946 hours	2004 Nissan; 3NICB51D64L482717	BC521444
2. 0945 - 1026 hours	2001 Lincoln; 5LMFU28R21LJ18539	BC521445
3. 1100 - 1127 hours	2002 Buick; 3G5DA03E22S572132	BC521446
4. 1249 - 1306 hours	2001 Volkswagen; 3VWSK69M01M137558	BC521447
5. 1310 - 1421 hours	2005 Chevrolet; KL1TD526X5B338394	BC521448
6. 1343 - 1452 hours	2000 Honda; 1HGCG1653YA028609	BC521449

FIRST CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

- 30. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which he knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows:
- a. Respondent certified under penalty of perjury on the vehicle inspection report for the 2003 Toyota truck, identified in paragraph 25 above, that the vehicle had passed inspection and was in compliance with applicable laws and regulations. In fact, Respondent conducted the inspection using clean-piping methods in order to issue a certificate for the vehicle and did not test or inspect the vehicle as required by Health & Saf. Code section 44012.
- b. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 through 6, identified in paragraph 29 above, that the applicable inspections were performed of the brake systems on the vehicles as specified by the Bureau and the vehicle

8

11

12 13

14 15

> 16 17

18

19 20

21

22 23

24 25

26

27

28 ///

///

manufacturer. In fact, Respondent failed to remove the wheels from any of the vehicles to measure the brake rotor/drum thickness or brake pad/lining thickness, and failed to perform a visual inspection of the brake systems on the vehicles.

- C. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 through 6, identified in paragraph 29 above, that each vehicle had a stopping distance of 20 feet from a speed of 20 miles per hour as a result of a road-test when, in fact, Respondent failed to road-test the vehicles.
- d. Respondent represented on the invoices for vehicles 1 through 6, identified in paragraph 29 above, that measurements were taken of the brake rotor/brake drum thickness and brake pad/brake lining thickness on the vehicles. In fact, Respondent failed to remove the wheels from any of the vehicles.

SECOND CAUSE FOR DISCIPLINE

(Fraud)

- 31. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that Respondent committed acts which constitute fraud, as follows:
- a. Respondent issued an electronic smog certificate of compliance for the 2003 Toyota truck, identified in paragraph 25 above, without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.
- b. Respondent charged the owners of vehicles 1 through 6, identified in paragraph 29 above, for performing the applicable inspections of the brake systems on the vehicles, and issued brake certificates representing that he had performed the inspections as specified by the Bureau and in accordance with the Vehicle Code. In fact, Respondent failed to conduct the inspections in compliance with Bureau Regulations or the Vehicle Code, as set forth in subparagraphs 30 (b) and (c) above.

///

THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with the Bus. & Prof. Code)

- 32. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that Respondent failed in a material respect to comply with provisions of that Code, as follows:
 - a. <u>Section 9889.16</u>: Respondent issued brake certificates for vehicles 1 through 6, identified in paragraph 29 above, when the vehicles had not been inspected in compliance with Bureau regulations or the requirements of the Vehicle Code.
 - b. Section 9889.22: Respondent willfully made false statements or entries on the brake certificates for vehicles 1 through 6, identified in paragraph
 29 above, as set forth in subparagraphs 30 (b) and (c).

FOURTH CAUSE FOR DISCIPLINE

(Violations of Regulations)

- 33. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that Respondent failed in a material respect to comply with provisions of California Code of Regulations, title 16, as follows:
 - a. <u>Section 3305, subdivision (a)</u>: Respondent failed to perform the inspections of the brake systems on vehicles 1 through 6, identified in paragraph 29 above, in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.
 - b. Section 3321, subdivision (c)(2): Respondent issued brake certificates as to vehicles 1 through 6, identified in paragraph 29 above, when the brake systems on the vehicles had not been tested or inspected, as set forth in subparagraphs 30 (a) and (b) above.

FIFTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Bus. & Prof. Code)

34. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code sections 9889.3, subdivision (a), and 9889.3, subdivision (h), in that Respondent violated the provisions of Bus. & Prof. Code sections 9889.16 and 9889.22 relating to Respondent's licensed activities, as set forth in paragraph 32 above.

SIXTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

35. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (c), in that Respondent failed to comply with the provisions of California Code of Regulations, title 16, sections 3305, subdivision (a), and 3321, subdivision (c)(2), as set forth in paragraph 33 above.

SEVENTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud, or Deceit)

36. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (d), in that Respondent committed acts involving dishonesty, fraud, or deceit whereby another was injured, as set forth in paragraph 31 above.

EIGHTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

37. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code sections 9889.3, subdivision (a), and 9889.3, subdivision (h), in that Respondent violated the provisions of Bus. & Prof. Code sections 9889.16 and 9889.22 relating to his licensed activities, as set forth in paragraph 32 above.

NINTH CAUSE FOR DISCIPLINE

(Violations of Regulations)

38. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (c), in that Respondent failed to

- c. <u>Section 3340.41, subdivision (c)</u>: Respondent entered false information into the emission inspection system by entering vehicle identification information or emission control system identification data for a vehicle other than the one being tested.
- d. <u>Section 3340.42</u>: Respondent failed to conduct the required smog tests on the 2003 Toyota truck, identified in paragraph 25 above, in accordance with the Bureau's specifications.

TWELFTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

41. Respondent's smog check station license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that Respondent committed a dishonest, fraudulent, or deceitful act whereby another is injured, as follows: Respondent issued an electronic smog certificate of compliance for the 2003 Toyota truck, identified in paragraph 25 above, without performing a bona fide inspection of the emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

THIRTEENTH CAUSE FOR DISCIPLINE

(Violations of the Motor Vehicle Inspection Program)

- 42. Respondent's advanced emission specialist technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (a), in that Respondent failed in a material respect to comply with provisions of that Code, as follows:
 - a. <u>Section 44012</u>: Respondent failed to perform the emission control tests on the 2003 Toyota truck, identified in paragraph 25 above, in accordance with procedures prescribed by the department.
 - b. <u>Section 44059</u>: Respondent willfully made false entries on the vehicle inspection report, as set forth in subparagraph 30 (a) above.

,,

FOURTEENTH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations Pursuant to the Motor Vehicle Inspection Program)

- 43. Respondent's advanced emission specialist technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (c), in that Respondent failed in a material respect to comply with provisions of California Code of Regulations, title 16, as follows:
 - a. <u>Section 3340.24, subdivision (c)</u>: Respondent falsely or fraudulently issued an electronic smog certificate of compliance for the 2003 Toyota truck, identified in paragraph 25 above.
 - b. Section 3340.30, subdivision (a): Respondent failed to inspect and test the 2003 Toyota truck, identified in paragraph 25 above, in accordance with Health & Saf. Code sections 44012 and 44035, and California Code of Regulations, title 16, section 3340.42.
 - c. <u>Section 3340.41, subdivision (c)</u>: Respondent entered false information into the emission inspection system by entering vehicle identification information or emission control system identification data for a vehicle other than the one being tested.
 - d. <u>Section 3340.42</u>: Respondent failed to conduct the required smog tests on the 2003 Toyota truck, identified in paragraph 25 above, in accordance with the Bureau's specifications.

FIFTEENTH CAUSE FOR DISCIPLINE

(Dishonesty, Fraud or Deceit)

44. Respondent's advanced emission specialist technician license is subject to disciplinary action pursuant to Health & Saf. Code section 44072.2, subdivision (d), in that Respondent committed a dishonest, fraudulent, or deceitful act whereby another is injured, as follows: Respondent issued an electronic smog certificate of compliance for the 2003 Toyota truck, identified in paragraph 25 above, without performing a bona fide inspection of the

emission control devices and systems on the vehicle, thereby depriving the People of the State of California of the protection afforded by the Motor Vehicle Inspection Program.

VIDEOTAPE SURVEILLANCE OF AUGUST 16, 2007

- 45. Complainant incorporates by reference as though fully set forth herein the allegations contained in paragraphs 26 through 28 above.
- 46. On August 16, 2007, the Bureau representative conducted a videotape surveillance operation of Respondent's facility. A review of the surveillance videotape and the brake certificates issued by Respondent revealed as follows: Respondent certified that he performed the applicable inspections of the brake system components on the vehicles identified below as specified by the Bureau and the vehicle manufacturer, and that each vehicle required 20 feet to stop at 20 mph. In fact, Respondent did not remove the wheels from any of the vehicles to measure the brake rotor/drum thickness or brake pad/lining thickness, did not perform a visual inspection of the brake systems on the vehicles, and did not road test any of the vehicles.

Time Vehicle Observed at Facility	Vehicle Certified & VIN or License No.	Brake Certificate Number
1. 1329 - 1408 hours	2006 Toyota; JTEZU14R360082935	BC533999
2. 1543 - 1549 hours	2000 Pontiac; 4MMZ714	BC534000

SIXTEENTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

- 47. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which he knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows:
- a. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 and 2, identified in paragraph 46 above, that the applicable inspections were performed of the brake systems on the vehicles as specified by the Bureau and the vehicle manufacturer. In fact, Respondent failed to remove the wheels from the vehicles to measure the

28 | /

brake rotor/drum thickness or brake pad/lining thickness and failed to perform a visual inspection of the brake systems on the vehicles.

- b. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 and 2, identified in paragraph 46 above, that the vehicles had a stopping distance of 20 feet from a speed of 20 miles per hour as a result of a road-test when, in fact, Respondent failed to road-test the vehicles.
- c. Respondent represented on the invoices for vehicles 1 and 2, identified in paragraph 46 above, that measurements were taken of the brake rotor/brake drum thickness and brake pad/brake lining thickness on the vehicles. In fact, Respondent failed to remove the wheels from the vehicles.

SEVENTEENTH CAUSE FOR DISCIPLINE

(Fraud)

48. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that Respondent committed acts which constitute fraud, as follows: Respondent charged the owners of vehicles 1 and 2, identified in paragraph 46 above, for performing the applicable inspections of the brake systems on the vehicles, and issued brake certificates representing that he had performed the inspections as specified by the Bureau and in accordance with the Vehicle Code. In fact, Respondent failed to conduct the inspections in compliance with Bureau Regulations or the Vehicle Code, as set forth in subparagraphs 47 (a) and (b) above.

EIGHTEENTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Bus. & Prof. Code)

- 49. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that Respondent failed in a material respect to comply with provisions of that Code, as follows:
 - a. <u>Section 9889.16</u>: Respondent issued brake certificates for vehicles 1 and 2, identified in paragraph 46 above, when the vehicles had not

comply with the provisions of California Code of Regulations, title 16, sections 3305, subdivision (a), and 3321, subdivision (c)(2), as set forth in paragraph 50 above.

TWENTY-SECOND CAUSE FOR DISCIPLINE

(Dishonesty, Fraud, or Deceit)

53. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (d), in that Respondent committed acts involving dishonesty, fraud, or deceit whereby another was injured, as set forth in paragraph 48 above.

TWENTY-THIRD CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

54. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code sections 9889.3, subdivision (a), and 9889.3, subdivision (h), in that Respondent violated the provisions of Bus. & Prof. Code sections 9889.16 and 9889.22 relating to his licensed activities, as set forth in paragraph 49 above.

TWENTY-FOURTH CAUSE FOR DISCIPLINE

(Violations of Regulations)

55. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (c), in that Respondent failed to comply with the provisions of California Code of Regulations, title 16, sections 3305, subdivision (a), and 3321, subdivision (c)(2), as set forth in paragraph 50 above.

VIDEOTAPE SURVEILLANCE OF AUGUST 21, 2007

- 56. Complainant incorporates by reference as though fully set forth herein the allegations contained in paragraphs 26 through 28 above.
- 57. On August 21, 2007, the Bureau representative conducted a videotape surveillance operation of Respondent's facility. A review of the surveillance videotape and the brake certificates issued by Respondent revealed as follows: Respondent certified that he performed the applicable inspections of the brake system components on the vehicles identified below as specified by the Bureau and the vehicle manufacturer, and that each vehicle required 20

feet to stop at 20 mph. In fact, Respondent did not remove the wheels from any of the vehicles to measure the brake rotor/drum thickness or brake pad/lining thickness, did not perform a visual inspection of the brake systems on the vehicles, and did not road test any of the vehicles.

Time Vehicle Observed at Facility	Vehicle Certified & VIN or License No.	Brake Certificate Number
1. 1115 - 1139 hours	2002 Jeep; 1J4GW58N62C304651	BC534010
2. 1144 - 1205 hours	2001 Kia; License #5LKG640	BC534011
3. 1145 - 1230 hours	2005 Nissan; 1N4AL11D15N478477	BC534012

TWENTY-FIFTH CAUSE FOR DISCIPLINE

(Untrue or Misleading Statements)

- 8. Respondent's registration is subject to disciplinary action pursuant to Bus. Prof. Code section 9884.7, subdivision (a)(1), in that Respondent made or authorized statements which he knew or in the exercise of reasonable care should have known to be untrue or misleading, as follows:
- a. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 through 3, identified in paragraph 57 above, that the applicable inspections were performed of the brake systems on the vehicles as specified by the Bureau and the vehicle manufacturer. In fact, Respondent failed to remove the wheels from the vehicles to measure the brake rotor/drum thickness or brake pad/lining thickness and failed to perform a visual inspection of the brake systems on the vehicles.
- b. Respondent certified under penalty of perjury on the brake certificates for vehicles 1 through 3, identified in paragraph 57 above, that the vehicles had a stopping distance of 20 feet from a speed of 20 miles per hour as a result of a road-test when, in fact, Respondent failed to road-test the vehicles.
- c. Respondent represented on the invoices for vehicles 1 through 3, identified in paragraph 57 above, that measurements were taken of the brake rotor/brake drum thickness and brake pad/brake lining thickness on the vehicles. In fact, Respondent failed to remove the wheels from the vehicles.

TWENTY-SIXTH CAUSE FOR DISCIPLINE

(Fraud)

Expondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(4), in that Respondent committed acts which constitute fraud, as follows: Respondent charged the owners of vehicles 1 through 3, identified in paragraph 57 above, for performing the applicable inspections of the brake systems on the vehicles, and issued brake certificates representing that he had performed the inspections as specified by the Bureau and in accordance with the Vehicle Code. In fact, Respondent failed to conduct the inspections in compliance with Bureau Regulations or the Vehicle Code, as set forth in subparagraphs 58 (a) and (b) above.

TWENTY-SEVENTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Bus. & Prof. Code)

- 60. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that Respondent failed in a material respect to comply with provisions of that Code, as follows:
 - a. <u>Section 9889.16</u>: Respondent issued brake certificates for vehicles 1 through 3, identified in paragraph 57 above, when the vehicles had not been inspected in compliance with Bureau regulations or the requirements of the Vehicle Code.
 - b. Section 9889.22: Respondent willfully made false statements or entries on the brake certificates for vehicles 1 through 3, identified in paragraph
 57 above, as set forth in subparagraphs 58 (a) and (b).

23 ///

24 ///

25 ///

26 ///

27 ///

TWENTY-EIGHTH CAUSE FOR DISCIPLINE

(Violations of Regulations)

- 61. Respondent's registration is subject to disciplinary action pursuant to Bus. & Prof. Code section 9884.7, subdivision (a)(6), in that Respondent failed in a material respect to comply with provisions of California Code of Regulations, title 16, as follows:
 - a. <u>Section 3305, subdivision (a)</u>: Respondent failed to perform the inspections of the brake systems on vehicles 1 through 3, identified in paragraph 57 above, in accordance with the specifications, instructions, and directives issued by the Bureau and the vehicle manufacturer.
 - b. Section 3321, subdivision (c)(2): Respondent issued brake certificates as to vehicles 1 through 3, identified in paragraph 57 above, when the brake systems on the vehicles had not been tested or inspected, as set forth in subparagraphs 58 (a) and (b) above.

TWENTY-NINTH CAUSE FOR DISCIPLINE

(Failure to Comply with the Bus. & Prof. Code)

62. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code sections 9889.3, subdivision (a), and 9889.3, subdivision (h), in that Respondent violated the provisions of Bus. & Prof. Code sections 9889.16 and 9889.22 relating to Respondent's licensed activities, as set forth in paragraph 60 above.

THIRTIETH CAUSE FOR DISCIPLINE

(Failure to Comply with Regulations)

63. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (c), in that Respondent failed to comply with the provisions of California Code of Regulations, title 16, sections 3305, subdivision (a), and 3321, subdivision (c)(2), as set forth in paragraph 61 above.

26 //

27 ///

THIRTY-FIRST CAUSE FOR DISCIPLINE

(Dishonesty, Fraud, or Deceit)

64. Respondent's official brake station license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (d), in that Respondent committed acts involving dishonesty, fraud, or deceit whereby another was injured, as set forth in paragraph 59 above.

THIRTY-SECOND CAUSE FOR DISCIPLINE

(Failure to Comply with the Code)

65. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code sections 9889.3, subdivision (a), and 9889.3, subdivision (h), in that Respondent violated the provisions of Bus. & Prof. Code sections 9889.16 and 9889.22 relating to his licensed activities, as set forth in paragraph 60 above.

THIRTY-THIRD CAUSE FOR DISCIPLINE

(Violations of Regulations)

66. Respondent's brake adjuster license is subject to disciplinary action pursuant to Bus. & Prof. Code section 9889.3, subdivision (c), in that Respondent failed to comply with the provisions of California Code of Regulations, title 16, sections 3305, subdivision (a), and 3321, subdivision (c)(2), as set forth in paragraph 61 above.

MATTERS IN AGGRAVATION

Respondent, Complainant alleges by way of aggravation, as follows: On September 2, 1999, pursuant to the Proposed Decision of the Administrative Law Judge adopted as the Decision of the Director in the disciplinary action titled *In the Matter of the Accusation Against: Rho's Auto Repair*, etc., Case No. 77/99-55, the Director revoked Respondent's registration, lamp and brake station licenses, and lamp and brake adjuster licenses effective October 4, 1999. The revocations were stayed and Respondent was placed on probation for a period of three years on terms and conditions. Respondent's registration, lamp and brake station licenses, and lamp and brake adjuster licenses were also suspended for ten days effective October 4, 1999.

2.0

68. The administrative law judge found that Respondent violated Bus. & Prof. Code sections 9884.7, subdivision (a)(1) (untrue or misleading statements), 9884.7, subdivision (a)(3) (failure to provide copy of the written estimate), 9884.7, subdivision (a)(4) (fraud), 9884.7, subdivision (a)(6) (failure to comply with Bus. & Prof. Code sections 9884.9, subdivision (a), 9889.16, and 9889.22), 9884.7, subdivision (a)(6) (failure to comply with California Code of Regulations, title 16, sections 3305, subdivision (a), 3316, subdivision (d)(2), 3316, subdivision (c)(2), and 3371), and 9889.3, subdivisions (a), (c), (d), and (h).

OTHER MATTERS

- 69. Pursuant to Bus. & Prof. Code section 9884.7, subdivision (c), the Director may refuse to validate, or may invalidate temporarily or permanently, the registrations for all places of business operated in this state by Respondent James Myong Hwan Rho, also known as Myong Rho, owner of Rho's Auto Repair, upon a finding that said Respondent has, or is, engaged in a course of repeated and willful violations of the laws and regulations pertaining to an automotive repair dealer.
- 70. Pursuant to Health & Saf. Code section 44072.8, if Smog Check Station License Number RC 156930, issued to Respondent James Myong Hwan Rho, also known as Myong Rho, owner of Rho's Auto Repair, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the Director.
- 71. Pursuant to Bus. & Prof. Code section 9889.9, if Official Brake Station License Number BS 156930, issued to Respondent James Myong Hwan Rho, also known as Myong Rho, owner of Rho's Auto Repair, is revoked or suspended, any additional license issued under this chapter in the name of said licensee, including, but not limited to, Official Lamp Station License Number LS 156930, may be likewise revoked or suspended by the Director.
- 72. Pursuant to Health & Saf. Code section 44072.8, if Advanced Emission Specialist Technician License Number EA 111627, issued to Respondent James Myong Hwan Rho, also known as Myong Rho, is revoked or suspended, any additional license issued under this chapter in the name of said licensee may be likewise revoked or suspended by the Director.

1	Hwan Rho, also known as Myong Rho, including, but not limited to, Official Lamp Station	
2	License Number LS 156930 and Lamp Adjuster License Number LA 111627;	
3	9. Ordering Respondent James Myong Hwan Rho, also known as Myong	
4	Rho, individually, and as owner of Rho's Auto Repair, to pay the Director of Consumer Affairs	
5	the reasonable costs of the investigation and enforcement of this case, pursuant to Business and	
6	Professions Code section 125.3;	
7	10. Taking such other and further action as deemed necessary and proper.	
8	DATED: 7/7/08	
9	Mm Mill	
10	SHERRY MEHL / Chief	
11	Bureau of Automotive Repair Department of Consumer Affairs	
12	State of California	
13	Complainant	
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		

03562-110-LA2007304661

phd; 06/12/2008